



Big Apple Automotive
 21775 US Hwy 18
 Apple Valley CA 92307
 Phone: 760-247-7255 ~ Fax: 760-247-7255
 hwy18@bigappleautomotive.com
 bigappleautomotive.com
 BAR #221023 EPA ID#CAL000295516

#37

Estimate

Bill To SVUSD/Dallas
 35320 Daggett Yermo Rd
 Yermo, CA 92398
 USA

Plate CA SVUSD
 Description 2005 Chevrolet Silverado 2500 HD Base V8 6.0l
 5967CC 364CID VIN U
 VIN 1GBHC24U35E227961
 Odometer 1 In / 0 Out

Home (760) 254-1344
 Email dwhitton@svusdk12.net

Appointment 06/14/2022 12:37 PM

Work Order # 115028
 Service Advisor JEREMY NICODEMUS
 Technician ANTHONY G

Concern

Engine Concern
 Concern? =
 Conditions? =
 Last Service? =

Inspection

Vehicle 360 Inspection
 40 Point Multi Inspection

Service

Replace Engine Assy With Reman Long Block. 3 Year 100k Mile Parts And Labor Warranty
 Remove And Replace Engine Long Block Assy

Labor		\$168.09 / Hour	\$2,403.70
Replace Engine Assy With Reman Long Block. 3 Year 100k Mile Parts And Labor Warranty	1 Unit	\$4,361.33 / Unit	\$4,361.33 S
Engine Install Kit			
Belts & Radiator Hoses	1 Unit	\$478.75 / Unit	\$478.75 S
Oil Filter			
Fuel Filter			
Air Filter			
Breather Filter			
Plug Wires			
Rotor			
Distributor Cap			
Spark Plugs			
Engine Coolant / Antifreeze DEXCOOL	3 Unit	\$34.63 / Unit	\$103.89 S
5W30 SYNTHETIC BLEND OIL SAE	6 Unit	\$3.32 / Unit	\$19.92 S
		Sub	\$7,367.59

Total Parts		
Total Labor		\$4,963.89
Total Before Taxes & Miscellaneous Charges		\$2,403.70
		\$7,367.59
(S) CA State Sales Tax	7.75 %	\$384.70
Grand Total		\$7,752.29

Estimate is based upon inspection at this time and does not cover additional parts or labor required to complete repairs. If additional work is necessary, my authorization will be secured prior to that additional work. This Estimate expires in 15 days. This shop is not responsible for loss or damage to vehicle or the articles left in vehicle. I hereby authorize the repairs shown on this estimate and authorize you to operate this vehicle for the purpose of testing and/or inspection. An express mechanic's lien is hereby granted. All sublet machine work is performed by Napa and exhaust is sublet to Howard's Muffler. Preventative maintenance or recommendations

are made according to the manufactures maintenance schedule. If the recommendations have been performed please advise the technician or service advisor at the time of recommendation. All parts shown are new unless otherwise noted. Tear Down Notice - I understand my vehicle will be reassembled within 5 days from date of this estimate if I decline repairs. I agree to pay storage of \$50 per day if vehicle is left more than 3 days after completion of repairs.

Date _____ Customer Signature _____

Authorization(s)

06/14/2022 2:02 PM	\$7,752.29	Replace Engine Assy With Reman Long Block. 3 Year 100k Mile Parts And Labor Warranty Engine Concern Vehicle 360 Inspection Authorized by SVUSD/Dallas
--------------------	------------	---

SVUSD/Dallas - SVUSD CA - 2005 Chevrolet Silverado 2500 HD Base [1GBHC24U35E227961]

**Vehicle 360 Inspection
40 Point Multi Inspection**



Big Apple Automotive
 21775 US Hwy 18
 Apple Valley CA 92307
 Phone: 760-247-7255 ~ Fax: 760-247-7255
 hwy18@bigappleautomotive.com
 bigappleautomotive.com
 BAR #221023 EPA ID#CAL000295516

#38

Estimate

Bill To SVUSD/Dallas
 35320 Daggett Yermo Rd
 Yermo, CA 92398
 USA

Plate CA NONE
 Description 2005 Chevrolet Silverado 2500 HD Base V8 6.0l
 5967CC 364CID VIN U
 VIN 1GBHC24U35E203532
 Odometer 212,792 In / 0 Out

Home (760) 254-1344
 Email dwhitton@svusdk12.net

Appointment 06/10/2022 10:46 AM

Work Order # 114989
 Service Advisor JEREMY NICODEMUS
 Technician ANTHONY G

Concern

Engine Concern
 School District Request Engine Estimate/ Attention Dallas.

Inspection

Vehicle 360 Inspection
 40 Point Multi Inspection

Service

Replace Engine Assy With Reman Long Block. 3 Year 100k Mile Parts And Labor Warranty

Remove And Replace Engine Long Block Assy

Labor			
Engine Assy With Reman Long Block. 3 Year 100k Mile	1 Unit	\$168.09 / Hour	\$2,403.70
Parts And Labor Warranty		\$4,361.33 / Unit	\$4,361.33 S
Engine Install Kit	1 Unit	\$478.75 / Unit	\$478.75 S
Belts & Radiator Hoses			
Oil Filter			
Fuel Filter			
Air Filter			
Breather Filter			
Plug Wires			
Rotor			
Distributor Cap			
Spark Plugs			
Engine Coolant / Antifreeze	3 Unit	\$34.63 / Unit	\$103.89 S
DEXCOOL			
5W30 SYNTHETIC BLEND OIL SAE	6 Unit	\$3.32 / Unit	\$19.92 FS
		Sub	\$7,367.59

Total Parts		
Total Labor		\$4,963.89
Total Before Taxes & Miscellaneous Charges		\$2,403.70
		<u>\$7,367.59</u>
(F) Fluid Disposal	\$0.50 Each	\$3.00
(S) CA State Sales Tax	7.75 %	\$384.70
Grand Total		<u>\$7,755.29</u>

Estimate is based upon inspection at this time and does not cover additional parts or labor required to complete repairs. If additional work is necessary, my authorization will be secured prior to that additional work. This Estimate expires in 15 days. This shop is not responsible for loss or damage to vehicle or the articles left in vehicle. I hereby authorize the repairs shown on this estimate and authorize you to operate this vehicle for the purpose of testing and/or inspection. An express mechanic's lien is hereby granted. All sublet machine work is performed by Napa and exhaust is sublet to Howard's Muffler. Preventative maintenance or recommendations

are made according to the manufactures maintenance schedule. If the recommendations have been performed please advise the technician or service advisor at the time of recommendation. All parts shown are new unless otherwise noted. Tear Down Notice - I understand my vehicle will be reassembled within 5 days from date of this estimate if I decline repairs. I agree to pay storage of \$50 per day if vehicle is left more than 3 days after completion of repairs.

Date _____ Customer Signature _____

Authorization(s)

06/10/2022 12:01 PM \$7,755.29

Email - Email - dwhitton@svusdk12.net
Engine Concern
Vehicle 360 Inspection
Replace Engine Assy With Reman Long Block. 3 Year 100k Mile Parts And Labor
Warranty
Authorized by SVUSD/Dallas

SVUSD/Dallas - NONE CA - 2005 Chevrolet Silverado 2500 HD Base [1GBHC24U35E203532]

Vehicle 360 Inspection
40 Point Multi Inspection



1139

Big Apple Automotive
 21775 US Hwy 18
 Apple Valley CA 92307
 Phone: 760-247-7255 ~ Fax: 760-247-7255
 hwy18@bigappleautomotive.com
 bigappleautomotive.com
 BAR #221023 EPA ID#CAL000295516

Estimate

Bill To SVUSD/Dallas
 35320 Daggett Yermo Rd
 Yermo, CA 92398
 USA

Plate CA SVUSD
 Description 2005 Chevrolet Silverado 2500 HD Base V8 6.0l
 5967CC 364CID VIN U
 VIN 1GBHC24U95E321827
 Odometer 1 In / 0 Out

Home (760) 254-1344
 Email dwhitton@svusdk12.net

Work Order # 115028
 Service Advisor JEREMY NICODEMUS
 Technician ANTHONY G

Appointment 06/14/2022 12:37 PM

Concern

Engine Concern

Concern? =
 Conditions? =
 Last Service? =

Inspection

Vehicle 360 Inspection
 40 Point Multi Inspection

Service

Replace Engine Assy With Reman Long Block. 3 Year 100k Mile Parts And Labor Warranty

Remove And Replace Engine Long Block Assy
 Labor

		\$168.09 / Hour	\$2,403.70
Replace Engine Assy With Reman Long Block. 3 Year 100k Mile Parts And Labor Warranty	1 Unit	\$4,361.33 / Unit	\$4,361.33 S
Engine Install Kit			
Belts & Radiator Hoses	1 Unit	\$478.75 / Unit	\$478.75 S
Oil Filter			
Fuel Filter			
Air Filter			
Breather Filter			
Plug Wires			
Rotor			
Distributor Cap			
Spark Plugs			
Engine Coolant / Antifreeze DEXCOOL	3 Unit	\$34.63 / Unit	\$103.89 S
5W30 SYNTHETIC BLEND OIL SAE	6 Unit	\$3.32 / Unit	\$19.92 S
		Sub	\$7,367.59

Total Parts		\$4,963.89
Total Labor		\$2,403.70
Total Before Taxes & Miscellaneous Charges		\$7,367.59
(S) CA State Sales Tax	7.75 %	\$384.70
Grand Total		\$7,752.29

Estimate is based upon inspection at this time and does not cover additional parts or labor required to complete repairs. If additional work is necessary, my authorization will be secured prior to that additional work. This Estimate expires in 15 days. This shop is not responsible for loss or damage to vehicle or the articles left in vehicle. I hereby authorize the repairs shown on this estimate and authorize you to operate this vehicle for the purpose of testing and/or inspection. An express mechanic's lien is hereby granted. All sublet machine work is performed by Napa and exhaust is sublet to Howard's Muffler. Preventative maintenance or recommendations

are made according to the manufactures maintenance schedule. If the recommendations have been performed please advise the technician or service advisor at the time of recommendation. All parts shown are new unless otherwise noted. Tear Down Notice - I understand my vehicle will be reassembled within 5 days from date of this estimate if I decline repairs. I agree to pay storage of \$50 per day if vehicle is left more than 3 days after completion of repairs.

Date _____ Customer Signature _____

Authorization(s)

06/14/2022 2:02 PM \$7,752.29

Replace Engine Assy With Reman Long Block. 3 Year 100k Mile Parts And Labor
Warranty
Engine Concern
Vehicle 360 Inspection
Authorized by SVUSD/Dallas

SVUSD/Dallas - SVUSD CA - 2005 Chevrolet Silverado 2500 HD Base [1GBHC24U95E321827]

Vehicle 360 Inspection
40 Point Multi Inspection



Big Apple Automotive
 21775 US Hwy 18
 Apple Valley CA 92307
 Phone: 760-247-7255 ~ Fax: 760-247-7255
 hwy18@bigappleautomotive.com
 bigappleautomotive.com
 BAR #221023 EPA ID#CAL000295516

H/48

Estimate

Bill To SVUSD/Dallas
 35320 Daggett Yermo Rd
 Yermo, CA 92398
 USA

Plate CA 1259904
 Description 2008 Chevrolet Silverado 2500 HD WT V8 6.0L
 5967CC 364CID VIN K
 VIN 1GBHC24K48E102101
 Odometer 212,792 In / 0 Out

Home (760) 254-1344
 Email dwhitton@svusdk12.net

Appointment 06/10/2022 10:46 AM

Work Order # 114989
 Service Advisor JEREMY NICODEMUS
 Technician ANTHONY G

Concern

Engine Concern
 School District Request Engine Estimate/ Attention Dallas.

Inspection

Vehicle 360 Inspection
 40 Point Multi Inspection

Service

Replace Engine Assy With Reman Long Block. 3 Year 100k Mile Parts And Labor Warranty

Remove And Replace Engine Long Block Assy

Labor			
Engine Assy With Reman Long Block. 3 Year 100k Mile	1 Unit	\$168.09 / Hour	\$2,403.70
Parts And Labor Warranty		\$4,199.99 / Unit	\$4,199.99 S
Engine Install Kit	1 Unit	\$802.50 / Unit	\$802.50 S
Belts & Radiator Hoses			
Oil Filter			
Fuel Filter			
Air Filter			
Breather Filter			
Plug Wires			
Rotor			
Distributor Cap			
Spark Plugs			
Engine Coolant / Antifreeze	3 Unit	\$34.63 / Unit	\$103.89 S
DEXCOOL			
5W30 SYNTHETIC BLEND OIL SAE	6 Unit	\$3.32 / Unit	\$19.92 FS
		Sub	\$7,530.00

Total Parts		
Total Labor		\$5,126.30
Total Before Taxes & Miscellaneous Charges		<u>\$2,403.70</u>
		\$7,530.00
(F) Fluid Disposal	\$0.50 Each	\$3.00
(S) CA State Sales Tax	7.75 %	<u>\$397.29</u>
Grand Total		\$7,930.29

Estimate is based upon inspection at this time and does not cover additional parts or labor required to complete repairs. If additional work is necessary, my authorization will be secured prior to that additional work. This Estimate expires in 15 days. This shop is not responsible for loss or damage to vehicle or the articles left in vehicle. I hereby authorize the repairs shown on this estimate and authorize you to operate this vehicle for the purpose of testing and/or inspection. An express mechanic's lien is hereby granted. All sublet machine work is performed by Napa and exhaust is sublet to Howard's Muffler. Preventative maintenance or recommendations

are made according to the manufactures maintenance schedule. If the recommendations have been performed please advise the technician or service advisor at the time of recommendation. All parts shown are new unless otherwise noted. Tear Down Notice - I understand my vehicle will be reassembled within 5 days from date of this estimate if I decline repairs. I agree to pay storage of \$50 per day if vehicle is left more than 3 days after completion of repairs.

Date _____ Customer Signature _____

Authorization(s)

06/10/2022 12:01 PM \$7,755.29

Email - Email - dwhitton@svusdk12.net
Engine Concern
Vehicle 360 Inspection
Replace Engine Assy With Reman Long Block. 3 Year 100k Mile Parts And Labor
Warranty
Authorized by SVUSD/Dallas

SVUSD/Dallas - 1259904 CA - 2008 Chevrolet Silverado 2500 HD WT [1GBHC24K48E102101]

Vehicle 360 Inspection
40 Point Multi Inspection